

Military Surface Deployment and Distribution Command
Customer/Carrier Advisory
May 26, 2016
CA-16-05/26-0053

Subject: GSA Global Supply- Safety Notification

Purpose: To inform all requisitioners, carriers, DLA Distribution/CCPs, Aerial Ports, and Ocean Terminals of the following: Incorrect item for NSN was provided to 47 requisitions going to 23 U.S. Army DODAACs.

Background: The tool provided under NSN 5110-00-595-8229 /P/N HKP0690C, from the orders dated February 15, 2016 through May 20, 2016, is the incorrect tool supplied. This is ONLY specific to the part number above under the described NSN, which was [ordered/provided] within the indicated dates. We have received information that utilization of this item for the intended purpose of cutting live electrical wire may cause serious personal injury and possible electrocution. **Immediate discontinued use of the item is recommended.** A replacement item will be supplied as soon as it is available in the supply system.

Be Advised: Do not use this device for cutting live wires, NSN 5110-00-595-8229 /P/N HKP0690C. Customer requisitions impacted by the incorrect item is as follows:

W22PEQ-5344-0013	W58GNS-6007-0626	W81U3R-5357-0026	WK4GDV-6050-0087
W34XYK-6051-0081	W58MKR-6053-0288	W81U3R-5365-0425	WK4GDV-6050-0090
W34XYK-6055-0135	W58MKR-6053-0292	W81U3R-5365-0442	WK4GDV-6050-0093
W34XYK-6063-0023	W58TLQ-6022-0084	W81U3R-5365-0443	WT4KDV-6004-0033
W34XYL-6030-0059	W80BTZ-6049-0012	W81U3R-6005-0024	WX3V9P-6049-0037
W34XYM-6030-0030	W80BTZ-6054-0031	W81WRD-6021-0034	
W44DQ1-6008-0181	W80BTZ-6054-0038	W81WRD-6022-0052	
W44DQ1-6047-0060	W80BTZ-6060-0034	W81XF9-6061-0065	
W44DQ1-6054-0095	W80BTZ-6060-0035	W90DY4-6058-0339	
W4546F-6033-0095	W80XYJ-6058-0028	W90DY4-6058-0879	
W4546F-6033-0102	W81U3R-5363-0058	W90DY4-6058-0880	
W4546F-6033-0103	W81E1D-6014-0150	W90HDC-5362-0007	
W45RNQ-6021-0051	W81U1K-6036-0076	W90HDC-6007-0040	
W58A6L-6063-2501	W81U1K-6048-0458	W90HDC-6033-0009	

Notification to all 23 requisitioners has been sent via email and phone calls. If you are in receipt of this item for any of the requisition numbers listed above, please contact the following POC so arrangements can be made to retrieve incorrect wire cutters.

POC: General Services Administration, GSA Branch Supervisor Traffic Management Branch (QSDQC), tel. 703-605-2977

Expiration: N/A